

Pavitt, John

From: Sue Sullivan <Sue.Sullivan@itd.idaho.gov>
Sent: Wednesday, January 08, 2014 2:36 PM
To: Pavitt, John
Subject: Followup questions
Attachments: 20140107160621275.pdf.pdf

John,

I looked into the three questions you asked on the phone.

1. Attached is the only document they had with the flooring contractor.
2. The break room measured 24x14 = 336 sq feet and the hallway was 31x4= 124 sq feet.
3. Paul Walker, the district Haz Mat coordinator was onsite but he does not have training in asbestos.

Sue Sullivan
Idaho Transportation Department
Environmental Program Manager
208 (334-8203)
sue.sullivan@itd.idaho.gov